
## 1892


## City of Aberdeen Sewer Clean Out Cap Broken / Missing Information

In the City of Aberdeen, it is the homeowner's responsibility to maintain their sewer cleanout to be in a working condition. This prevents possible sewer backups from debris entering the system. Also, it complies

with the City Code Section 450-40 stating "No person(s) shall make connection...or other sources of surface runoff or groundwater to a building sewer or building drain which, in turn, is connected directly or indirectly to a public sanitary sewer. "

Cleanout caps are frequently damaged by lawn mowers and/or buried by landscaping work. These caps can range in size and be made from either plastic or metal.







Clean Out Cap is Missing



Clean Out Cap is Broken